

October 1, 1963

Subject: Driftsight Power Changer Modification

- 1.) Approval of the attached ECP will authorize service bulletin.
- 2.) ECP form was used to indicate cost and delivery factors.
- 3.) All work on Driftsight to be handled at field site under direction of PECO tech rep.
- 4.) If area capability allows the replacement of existing vehicle cable plug and installation and potting of new plug by military personnel, no LAC participation is necessary.
- 5.) If LAC electricians are required to handle installation of new cable plug we suggest that participation directed by local command is best method. New cable plug is included in proposed service bulletin.



STATINTL